

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,327,013 B2  
APPLICATION NO. : 10/743522  
DATED : February 5, 2008  
INVENTOR(S) : Shibata et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On Title page, item (57), delete the ABSTRACT in its entirety and substitute therefor:

-- In a stencil mask, a conductive thin film has first openings in it. An insulating film is formed in the region of the conductive thin film excluding the first openings. A conductive support is formed on the insulating film. A second opening goes through the conductive support and insulating film and reaches the surface of the conductive thin film. A conducting member is formed in the second opening. The conducting member connects the conductive support and conductive thin film electrically. --

Claim 20, column 14, line 3, change "region the" to -- region, the --.

Signed and Sealed this

Twentieth Day of May, 2008



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*